

INDIA'S MOST TRUSTWORTHY AUTO INSPECTION & VERIFICATION SERVICE



AI & Tech Driven Inspection & Certification



Independent



Unbiased



Objective



Comprehensive



Scientific

- a service by **droom**

ECO INSPECTION REPORT

India's Most Comprehensive And Scientific Vehicle Inspection Service

Ordered By



Anant Goel

10 / 01 / 2021

Gurgaon


Inspected By



Mitesh Karwa

- Verified Technician
- 36+ Vehicle Treated
- 4+ Years Experience

Audi A4 Premium Plus, 2019



₹ 34,07,519

Automobile from individual in good condition is valued

Vehicle Information

| | | | |
|------------------|--------------|--------------------|-------------------------------------|
| Make | Audi | Transmission Type | Automatic |
| Model | A4 | Registration Type | Private |
| Year | 2019 | Registration No. | DL10CG3657 |
| Trim | Premium Plus | VIN/Chassis Number | 16191 |
| Exterior Color | Terra Gray | Kms Run | 25105 |
| Interior Color | Beige | Manufacturing Date | 2022-05-20 |
| Body Type | Sedan | Registration Date | 2022-07-15 |
| Fuel Type | Petrol | Insurance Expiry | 2020-7-14 |
| Engine CC | 200 | CNG Validity | 2025-6-20 |
| Engine No. | 452390 | Location | Janak Puri |
| Number of Owners | 2 | Engine Sound Link | Listen Engine Sound |

Key Highlights

| | | | |
|--------------------------|----------------|--------------------------|----|
| Flood Damage | No | Insurance Copy Available | No |
| Tyre Life Remaining (KM) | 25,105 | Service Logs Available | No |
| Dent | Yes | Bank Hypothecation | No |
| Major Accidents | No | Bank NOC | No |
| RC Copy Available | Yes (Original) | | |

ECO Repair Estimate

Total Repair Estimate ₹ 10250



ECO OVERALL SCORE BREAKDOWN

Interior



Exterior



Wheel



Hood



Test Drive



EXTERIOR

Vehicle Exterior View and Condition

0 Critical
 2 Bad
 4 Below Average
 6 Average
 8 Good
 10 Excellent

| | | |
|--|--------------|---|
| Grille 6 | | |
| Front Bumper 8 | 1999 X 60 7D | Paint Condition 10 |
| Front Windshield 8 | | Hood 4 |
| Left Fender 4 | | Antenna 10 |
| LH Side View Mirror 10 | | RH Fender 10 |
| Roof 10 | | RH Side View Mirror 6 |
| LH Front Door 10 | | Pillars 10 |
| LH Running Board 6 | | RH Front Door 8 |
| LH Rear Door 10 | | RH Running Board 6 |
| Fuel Lid 2 | | RH Rear Door 4 |
| LH Quarter Panel 6 | | RH Quarter Panel 8 |
| Trunk Lid / Tail Gate 10 | DL 09 K 6661 | Body Rust 8 |
| | | Rear Winshield 8 |
| | | Rear Bumper 10 |

| | |
|---|---|
| Front License Plate is available? | ✓ |
| License Plates are HSRP complaint? | ✗ |
| Head Lights are working? | ✓ |
| Turn Signal lamps are working? | ✗ |
| Hazard Lamps are working? | ✓ |
| License plate light is working? | ✓ |
| Rear windshield wiper is working in good condition? | ✓ |

| | |
|--|-----|
| Rear License Plate is available? | ✓ |
| HSRP colour sticker is available? | ✗ |
| Tail Lights are working? | ✓ |
| Fog Lamps are working? | N/A |
| Break lights are working? | ✓ |
| Front windshield wiper is working in good condition? | ✓ |
| Reverse parking lights are working? | ✓ |



Exterior Images

FRONT VIEW



REAR VIEW



LEFT SIDE VIEW



RIGHT SIDE VIEW



LEFT FRONT CORNER VIEW



LEFT REAR CORNER VIEW



RIGHT FRONT CORNER VIEW



RIGHT REAR CORNER VIEW



INTERIOR

Vehicle Interior View and Condition

0 Critical
 2 Bad
 4 Below Average
 6 Average
 8 Good
 10 Excellent

| | |
|---|---|
| Reverse Parking Camera 6 | Ceiling 8 |
| Reverse Parking Sensors 10 | Dashboard & Instrument Panel 8 |
| Door Hinges 0 | Odometer 10 |
| Front LH Door Panel 8 | Front RH Door Panel 8 |
| Air Conditioning System 8 | Heating System 6 |
| Rear LH Door Panel 4 | Pedals 8 |
| | Rear RH Door Panel 4 |

| | |
|--|---|
| Music System is working properly? ✓ | Speakers are working properly? ✓ |
| Navigation System is working properly? ✗ | Steering Mounted Controls are working properly? N/A |
| Horn is loud & clear? ✓ | Handbrake is working properly? ✓ |
| Sun Visors are working properly? ✗ | All Cabin lights are working properly? N/A |
| Luggage Compartment light is working properly? N/A | Central Lock is working? ✓ |
| Power Windows are working? ✓ | Floor Mats are available? ✓ |
| Carpets are in good condition? ✓ | Seat Covers are in good condition? ✓ |
| Front Seat Belts are working properly? N/A | Rear Seat Belts are working properly? N/A |
| Boot Lever is working properly? ✗ | Fuel Lid Lever is working properly? ✓ |
| Front De-Fogger is available? ✓ | Bonnet Lever is working properly? ✗ |
| USB port is available? ✓ | Rear De-Fogger is available? ✓ |
| Rear view mirror is functional? ✓ | Glove box light is working? ✓ |
| Passenger side seat adjustments are working properly? ✓ | Driver side seat adjustments are working properly? ✓ |
| Odometer/Trip switches are working properly? ✓ | |



Interior Images

DASHBOARD VIEW



CLUSTER METER VIEW



FRONT SEATS



REAR SEATS



GLOVE BOX



INTERIOR REAR VIEW



INTERIOR FRONT VIEW




INTERIOR DOOR PANEL







WHEELS

Wheel View and Condition



Wheels Images



Miscellaneous

| | | | |
|--|---|------------------------------|---|
| Airbags are Available? | ✓ | Cruise Control is Available? | ✓ |
| VIN/Chassis Number matching with document? | ✗ | Medical Kit available? | ✗ |
| Vehicle jack and wrench available? | ✓ | MIL/Engine Light is OFF? | ✓ |

Images



Documents



NEED ATTENTION

Interior

CENTRAL LOCK



Remarks: Central Lock Not Working
Repair Estimate: ₹ 600

POWER WINDOW



Remarks: Power Window Not Working
Repair Estimate: ₹ 600

Wheel

FRONT TYRES



Remarks: Front tyres are not in a good condition
Repair Estimate: ₹ 600

SPARE TYRES



Remarks: Spare tyres are not in a good condition
Repair Estimate: ₹ 600

Exterior

FOG LAMPS



Remarks: Major cracks in Fog Lamps
Repair Estimate: ₹ 900

LEFT FRONT DOOR



Remarks: Scratches/Dents in Front Door
Repair Estimate: ₹ 900



Other Images

GRILLE



FRONT BUMPER



REAR BUMPER



BONNET HOOD



FRONT WINDSHIELD



REAR WINDSHIELD



LEFT SIDE MIRROR



RIGHT SIDE MIRROR



LH FRONT DOOR



RIGHT FRONT DOOR



LEFT REAR DOOR



RIGHT REAR DOOR



LEFT FENDER



RIGHT FENDER



LEFT QUARTER PANEL



Other Images

RIGHT QUARTER PANEL



BOOT TRUNK LID



ROOF



FRONT LICENSE PLATE



REAR LICENSE PLATE



HSRP COLOUR STICKER



FRONT WINDSHIELD WIPER



REAR WINDSHIELD WIPER



ODOMETER



POWER WINDOWS



REAR VIEW MIRROR



ENGINE COMPARTMENT



UNDERCARRIAGE



BATTERY



TRUNK LID



Other Images



Overall Comments

Car is in average condition

Disclaimer

This inspection report was generated by ECO, a service arm of Droom Technology limited. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.





www.droom.in/eco